

CaRPM ASSESSMENT REPORT



Report Summary

Report Time	20/10/21 08:49	Inspector Name:	Expat Auto Chiang Mai
License Plate:	2867	Car Name:	Nissan
Year of Manufacture:	0	Odometer Reading:	-

SYSTEM STATUS

Air and Fuel Mixing System	Ok	Fuel Pump and Injectors	Ok
Camshaft and Crankshaft Sensors	Ok	Transmission	Ok
Speed Control System	Ok	Emission Check System	Ok
Engine Control Module (ECU)	Ok	Body Control Module (BCM)	Ok
Chassis Control System	Ok	Communication Network System	Ok

Faults

NO FAULTS HERE, PLEASE CHECK APPENDIX FOR MORE INFORMATION



CAR MAINTENANCE

Fuel Trim:	Pass	Engine Misfire:	Pass
Fuel System:	Data Not Available	Engine Knocking:	Pass
Battery Voltage:	12.5 V	Idling RPM:	Data Not Available
Overheating:	Data Not Available		