

CaRPM ASSESSMENT REPORT



Report Summary

Report Time	12/01/22 14:36	Inspector Name:	Expat Auto Chiang Mai
License Plate:	8342	Car Name:	Toyota
Year of Manufacture:	0	Odometer Reading:	-

SYSTEM STATUS

Air and Fuel Mixing System	Ok	Fuel Pump and Injectors	Ok
Camshaft and Crankshaft Sensors	Ok	Transmission	Ok
Speed Control System	Ok	Emission Check System	Ok
Engine Control Module (ECU)	Ok	Body Control Module (BCM)	Ok
Chassis Control System	Ok	Communication Network System	Ok

Faults



CAR MAINTENANCE

Fuel Trim:	Pass	Engine Misfire:	Pass
Fuel System:	Pass	Engine Knocking:	Pass
Battery Voltage:	12.2 V	Idling RPM:	Pass
Overheating:	No		